



Polished Stainless Steel Individual Kits Intake Manifold Bolts

Diamond Engineering
1527 Pine Avenue
Holly Hill, Florida 32117
Phone: (386) 677-9093
Fax: (386) 677-2384
Email: info@depss.com

Intake Manifold Bolts	O.E.	Socket Cap	12 Point
All Models 1984-89 & 1995-10	---	---	PB537S Intake Manifold Bolts \$21.95

Diamond Engineering | 1527 Pine Avenue | Holly Hill, Florida 32117
Phone: (386) 677-9093 | Fax: (386) 677-2384 | Email: info@depss.com
© 2018 Diamond Engineering All Rights Reserved.