



# Polished Stainless Steel Individual Kits

## Primary & Inspection covers

Diamond Engineering  
 1527 Pine Avenue  
 Holly Hill, Florida 32117  
 Phone: (386) 677-9093  
 Fax: (386) 677-2384  
 Email: info@depss.com

Primary & Inspection covers	O.E.	Socket Cap	12 Point	Groove
Dyna Models 2006-10, Softail Models 2007-10 (except Rockers & FXSTSSE3 2009)	<b>DE5204P</b> Primary & Inspection Cover, Dyna 2006 <b>\$47.99</b>	---	<b>PB566S</b> Primary & Inspection Cover, Dyna 2006 <b>\$92.49</b>	<b>DE5204GP</b> Primary, Inspection Covers <b>\$51.49</b>
Dyna Models 1999-05, Softail Models 2000-06 (Also includes 2 visible inner primary bolts)	<b>DE5007P</b> Primary & inspection covers Softail 00-06, Dyna 99-05 <b>\$48.49</b>	---	<b>PB564S</b> Primary Cvr ST 2000-01 Dyna 1999-01 <b>\$92.99</b>	<b>DE5007GP</b> Primary & inspection covers Softail 00-06, Dyna 99-05 <b>\$53.99</b>
Dyna Models 1995 - 98, Softail Models 1995 - 99 (Also includes 2 visible inner primary bolts)	<b>DE5005P</b> Primary & inspection covers Softail 95-99, Dyna 95-98 <b>\$51.49</b>	---	<b>PB563S</b> Primary Cvr ST 95-99 Dyna 95-98 <b>\$88.49</b>	<b>DE5005GP</b> Primary & inspection covers Softail 95-99, Dyna 95-98 <b>\$56.99</b>
Dyna Models 1991-94, Softail Models 1989-94 (Also includes 2 visible inner primary bolts)	<b>DE5004P</b> Primary & inspection covers Softail & Dyna 89-94 <b>\$45.49</b>	---	<b>PB562S</b> Primary Cvr ST & Dyna 1989-94 <b>\$82.49</b>	---
Softail Models 1984-88 (Also includes 2 visible inner primary bolts)	<b>DE5003P</b> Primary & inspection covers Softail 84-88 <b>\$38.49</b>	---	<b>PB561S</b> Primary Cvr ST 1984-88 <b>\$65.49</b>	---
Touring Models 2007-10	<b>DE5273P</b> Primary & Inspection Cover, Touring Models 2007 <b>\$60.49</b>	---	<b>PB592S</b> Primary & Inspection Cover, Touring Models 2007 <b>\$93.49</b>	<b>DE5273GP</b> Primary, Inspection Covers <b>\$67.99</b>
Touring Models 1999-06 (Also includes 2 visible inner primary bolts)	<b>DE5008P</b> Primary & inspection covers Touring 99-06 <b>\$43.49</b>	---	<b>PB565S</b> Primary Cvr FLT 1999-01 <b>\$82.99</b>	<b>DE5008GP</b> Primary & inspection covers Touring 99-06 <b>\$47.49</b>



## Polished Stainless Steel Individual Kits Primary & Inspection covers

Diamond Engineering  
1527 Pine Avenue  
Holly Hill, Florida 32117  
Phone: (386) 677-9093  
Fax: (386) 677-2384  
Email: info@depss.com

FXR & Touring Models 1985-98 (Also includes 2 visible inner primary bolts)	<b>DE5002P</b> Primary & inspection covers FXR & FLT 85-98 <b>\$40.99</b>	---	<b>PB560S</b> Primary Cvr FXR & FLT 1985-98 <b>\$76.99</b>	---
1980-84 5 Speeds (Except FL 1980-83) (Also includes 2 visible inner primary bolts)	<b>DE5001P</b> Primary & inspection covers 1980-84 5 spd <b>\$45.49</b>	---	---	---
1970-85 4 Speeds (Also includes 2 visible inner primary bolts)	<b>DE5000P</b> Primary & inspection covers 1970-85 4 spd <b>\$38.49</b>	---	<b>PB558S</b> Primary Cvr 4 spd 1970-85 <b>\$83.99</b>	---
FL models 1936-65	---	---	---	---
Rockers 2008-10, FXSTSSE3 2009	<b>DE5341P</b> Primary & inspection cover Rockers <b>\$52.99</b>	---	<b>PB841S</b> Primary & inspection cover Rockers <b>\$87.99</b>	<b>DE5341GP</b> Primary & inspection cover Rockers <b>\$64.99</b>

**Diamond Engineering** | 1527 Pine Avenue | Holly Hill, Florida 32117  
Phone: (386) 677-9093 | Fax: (386) 677-2384 | Email: info@depss.com  
© 2012 Diamond Engineering All Rights Reserved.