



Polished Stainless Steel Individual Kits

Primary & Inspection covers

Diamond Engineering
 1527 Pine Avenue
 Holly Hill, Florida 32117
 Phone: (386) 677-9093
 Fax: (386) 677-2384
 Email: info@depss.com

Primary & Inspection covers	O.E.	Socket Cap	12 Point	Groove
Dyna Models 2006-10, Softail Models 2007-10 (except Rockers & FXSTSSE3 2009)	DE5204P Primary & Inspection Cover, Dyna 2006 \$47.99	---	PB566S Primary & Inspection Cover, Dyna 2006 \$96.95	DE5204GP Primary, Inspection Covers \$51.49
Dyna Models 1999-05, Softail Models 2000-06 (Also includes 2 visible inner primary bolts)	DE5007P Primary & inspection covers Softail 00-06, Dyna 99-05 \$48.49	---	PB564S Primary Cvr ST 2000-01 Dyna 1999-01 \$97.49	DE5007GP Primary & inspection covers Softail 00-06, Dyna 99-05 \$53.99
Dyna Models 1995 - 98, Softail Models 1995 - 99 (Also includes 2 visible inner primary bolts)	DE5005P Primary & inspection covers Softail 95-99, Dyna 95-98 \$51.49	---	PB563S Primary Cvr ST 95-99 Dyna 95-98 \$92.95	DE5005GP Primary & inspection covers Softail 95-99, Dyna 95-98 \$56.99
Dyna Models 1991-94, Softail Models 1989-94 (Also includes 2 visible inner primary bolts)	DE5004P Primary & inspection covers Softail & Dyna 89-94 \$45.49	---	PB562S Primary Cvr ST & Dyna 1989-94 \$86.49	---
Softail Models 1984-88 (Also includes 2 visible inner primary bolts)	DE5003P Primary & inspection covers Softail 84-88 \$38.49	---	PB561S Primary Cvr ST 1984-88 \$67.95	---
Touring Models 2007-10	DE5273P Primary & Inspection Cover, Touring Models 2007 \$60.49	---	PB592S Primary & Inspection Cover, Touring Models 2007 \$97.95	DE5273GP Primary, Inspection Covers \$67.99
Touring Models 1999-06 (Also includes 2 visible inner primary bolts)	DE5008P Primary & inspection covers Touring 99-06 \$43.49	---	PB565S Primary Cvr FLT 1999-01 \$86.95	DE5008GP Primary & inspection covers Touring 99-06 \$47.49



Polished Stainless Steel Individual Kits Primary & Inspection covers

Diamond Engineering
1527 Pine Avenue
Holly Hill, Florida 32117
Phone: (386) 677-9093
Fax: (386) 677-2384
Email: info@depss.com

FXR & Touring Models 1985-98 (Also includes 2 visible inner primary bolts)	DE5002P Primary & inspection covers FXR & FLT 85-98 \$40.99	---	PB560S Primary Cvr FXR & FLT 1985-98 \$79.95	---
1980-84 5 Speeds (Except FL 1980-83) (Also includes 2 visible inner primary bolts)	DE5001P Primary & inspection covers 1980-84 5 spd \$45.49	---	---	---
1970-85 4 Speeds (Also includes 2 visible inner primary bolts)	DE5000P Primary & inspection covers 1970-85 4 spd \$38.49	---	PB558S Primary Cvr 4 spd 1970-85 \$87.95	---
FL models 1936-65	---	---	---	---
Rockers 2008-10, FXSTSSE3 2009	DE5341P Primary & inspection cover Rockers \$52.99	---	PB841S Primary & inspection cover Rockers \$91.95	DE5341GP Primary & inspection cover Rockers \$64.99

Diamond Engineering | 1527 Pine Avenue | Holly Hill, Florida 32117
Phone: (386) 677-9093 | Fax: (386) 677-2384 | Email: info@depss.com
© 2018 Diamond Engineering All Rights Reserved.